



draft 3				seattle wayfinding system		04.17.2003	
100% ready				phase I kiosks			
PD-07		PD-13		PD-19		PD-24	
Location:	Pine, south side, between 6th and 5th	Location:	Pike, south side, between 3rd and 4th	Location:	Pike, north side, next to bus shelter, by Seattle's Best Coffee	Location:	1st, west side, corner of Marion and 1st
Mount:	Two bulb lamp	Mount:	Three bulb lamp			Mount:	Designated post
Sides:	Downtown/Downtown	Sides:	Downtown/Downtown	Mount:	Two bulb lamp	Sides:	Downtown/South Downtown
Damage:	No	Damage:	No	Sides:	Downtown/Downtown	Damage:	No
Comments:	Located by Starbucks	Comments:	Next to buss station. This area was very busy, but no one looked at the sign.	Damage:	No	Comments:	Only kiosk with a South Downtown panel.
PD-08		PD-14		PD-20		PD-25	
Location:	Pine, north side, between 4th and 5th	Location:	Union, north side, between 7th and underpass	Location:	1st, west side, between Pike and Union	Location:	Alaskan Way, east side, between Wall and Vine, closer to Wall
Mount:	Two bulb lamp	Mount:	Lamp	Mount:	3 bulb lamp	Mount:	Designated post
Sides:	Downtown/Downtown	Sides:	Downtown/Downtown	Sides:	Downtown/Downtown	Sides:	Downtown/Waterfront
Damage:	Yes	Damage:	Yes	Damage:	Yes	Damage:	No
Comments:	There was a sticker on one side. This kiosk was located next to a crosswalk – good idea.	Comments:	There are few oportunities for use at this site. There was a rust on the porcelain panel.	Comments:	There was a sticker on one side.	Comments:	The kiosk is less noticeable than the Bell St. Pier signs along Alaskan Way.
PD-09		PD-15		PD-21		PD-26	
This sign was covered due to construction.		Location:	Union, north side, between 6th and 5th.	Location:	1st, east side, between University and Union	Location:	Alaskan Way, east side, between Bell and Blanchard, near the corner of Bell
		Mount:	Lamp	Mount:	Museum light	Mount:	Designated post
PD-10		Sides:	Downtown/Downtown	Sides:	Downtown/Downtown	Sides:	Downtown/Waterfront
Location:	Pike, north side, between 6th and 7th	Damage:	No	Damage:	Yes	Damage:	No
Mount:	Three bulb lamp	Comments:	An area of sign clutter. The kiosk is surrounded signs and banners. The northeast side was blocked by a City Center parking sandwich board.	Comments:	This kiosk is mounted on a museum light. There was a sticker on one side.	Comments:	This kiosk is too close to the trolly railing. The map was parallel to the sidewalk and the ferry sign was on the wrong side.
Sides:	Downtown/Downtown	PD-16		PD-22		PD-27	
Damage:	No	Location:	Pine, north side, between 2nd and 3rd	Location:	1st, west side, at the intersection of 1st and Seneca	Location:	Alaskan Way, east side, in the middle of the path to the stairs going up to the market.
Comments:	Banners are hanging from the post and two newspaper boxs are located in-front of the sign. The sign's condition suggests repeative banging by one of the boxes, causing a gash in the porcelain panel (rust is visible).	Mount:	Two bulb lamp	Mount:	Three bulb lamp	Mount:	Designated post
PD-11		Sides:	Downtown/Downtown	Sides:	Downtown/Downtown	Sides:	Downtown/Waterfront
Location:	Pike, south side, between 5th and 6th	Damage:	Yes	Damage:	Yes, there was not a photo taken. Only sticker residue was visible.	Damage:	No
Mount:	Three bulb lamp	Comments:	There was a sticker on one side.	Comments:	This kiosk was on a light post that also housed a traffic light, a one way sign, and pedestrian crossing lights.	Comments:	Good location. Two people stoped to reference the sign, only glancing at the Downtown side (they were facing east), then continued towards the market.
Sides:	Downtown/Downtown	PD-17		PD-23		PD-28	
Damage:	No	Location:	1st, east side, between Stewart and Virginia	Location:	1st, east side, just after Seneca and before Spring	Location:	Western, west side, at the intersection of Western and Marion
Comments:	A banner is attached to the light post	Mount:	Designated post	Mount:	Lamp	Mount:	Designated post
PD-12		Sides:	Downtown/Downtown	Sides:	Downtown/Downtown	Sides:	Downtown/Waterfront
Location:	Pike, north side, between 4th and 5th	Damage:	No	Damage:	Yes	Damage:	Yes
Mount:	Three bulb lamp	Comments:	There was a sign on top of the kiosk	Comments:	There was a sticker on one side.	Comments:	Two stickers on two sides. This location had an unsafe street crossing. The sign is parallel to the sidewalk.
Sides:	Downtown/Downtown	PD-18					
Damage:	No	Location:	Pine, south side, between 1st and 2nd				
Comments:	No comments	Mount:	Two bulb lamp				
		Sides:	Downtown/Downtown				
		Damage:	No				
		Comments:	This sign was slightly hidden by trees.				





PD-01(2.23)



PD-01 (2.24)



PD-01 (2.25)



PD-01 (2.26)



PD-02 (2.18)




PD-02 (2.19)





PD-02 (2.20)



PD-02 (2.22)



PD-03 (2.13)



PD-03 (2.14)



PD-03 (2.15)



PD-03 (2.16)



PD-03 (2.17)



PD-05 (2.10)



PD-05 (2.11)



PD-05 (2.12)



PD-06 (2.27)



PD-06 (2.28)





PD-26 (2.29)



PD-07 (2.30)



PD-07 (2.31)



PD-07 (3.01)



PD-08 (3.02)



PD-08 (3.03)



PD-08 (3.04)



PD-08 (3.05)



PD-10 (1.29)



PD-10 (1.30)



PD-10 (2.01)



PD-10 (2.02)





PD-11 (1.26)



PD-11 (1.27)



PD-11 (1.28)



PD-12 (1.23)



PD-12 (1.24)



PD-12 (1.25)



PD-13 (1.20)



PD-13 (1.21)



PD-13 (1.22)



PD-14 (2.06)



PD-14 (2.07)



PD-14 (2.08)





PD-14 (2.09)



PD-15 (2.03)



PD-15 (2.04)



PD-15 (2.05)



PD-16 (3.06)



PD-16 (3.07)



PD-16 (3.08)



PD-16 (3.09)



PD-17 (5.01)



PD-17 (5.02)



PD-17 (5.03)



PD-18 (3.10)





PD-18 (3.11)



PD-18 (3.12)



PD-19 (1.17)



PD-19 (1.18)



PD-19 (1.19)



PD-20 (3.13)



PD-20 (3.14)



PD-20 (3.15)



PD-20 (3.16)



PD-21 (3.17)



PD-21 (3.18)



PD-21 (3.19)





PD-21 (3.20)



PD-22 (3.21)



PD-22 (3.22)



PD-22 (3.23)



PD-23 (3.24)



PD-23 (3.25)



PD-23 (3.26)



PD-23 (3.27)



PD-24 (5.04)



PD-24 (5.05)



PD-24 (5.06)



PD-25 (1.04)





PD-25 (1.05)



PD-25 (1.06)



PD-26 (1.11)



PD-26 (1.12)



PD-26 (1.13)



PD-27 (1.14)



PD-27 (1.15)



PD-27 (1.16)



PD-28 (3.29)



PD-28 (4.01)



PD-28 (4.02)



PD-28 (4.03)